



Product Discontinuance Notice - PDN 10_0041 Rev. A

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

ADM1066 - Discontinuation of Lead(Pb) Bearing Models

Publication Date: 02-Jul-2010

Last Time Buy Date: 01-Dec-2010

Last Time Ship Date: 01-Jun-2011

Reason For Discontinuance

Elimination is due to decreased activity of ADM1066 lead(Pb) bearing models.
Manufacturing Line Shutdown is reason for shorter than standard LTB and LTS dates.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com	Europe: PDN_Europe@analog.com	Japan: PDN_Japan@analog.com
		Rest of Asia: PDN_ROA@analog.com

PDN 10_0041 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADM1066ACP	ADM1066	ADM1066ACPZ	Yes	Direct replacement
ADM1066ACP-REEL	ADM1066	ADM1066ACPZ-REEL7	Yes	Direct replacement
ADM1066ACP-REEL7	ADM1066	ADM1066ACPZ-REEL7	Yes	Direct replacement

Appendix A - PDN 10_0041 Revision History

Rev	Publish Date	Rev Description
Rev. -	22-Mar-2010	Initial Release
Rev. A	02-Jul-2010	Revise Last Time Buy and Last Time Ship Dates to reflect the Supplier Pb Line Shutdown in Korea. (Amkor Technologies).

Analog Devices, Inc. Proprietary Information

DocId:193 Layout Rev:1 Parent DocId:None