



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000967

DATE: 21-May-2019

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX11131ATI+T	N/A			Part reactivated from prior notice: M000969I
Reactivation	MAX5171AEEE+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6043BAUT33+	N/A			Part reactivated from prior notice: M000876I
Reactivation	MAX6043BAUT33+	N/A			Part reactivated from prior notice: M000876I
Reactivation	MAX6043BAUT33+T	N/A			Part reactivated from prior notice: M000876I
Reactivation	MAX6043BAUT33+T	N/A			Part reactivated from prior notice: M000876I
Reactivation	MAX6071AAUT41+	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX6071AAUT41+T	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX8891EXK15+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX8891EXK15+T	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX9120ESA+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX9120ESA+T	N/A			Part reactivated from prior notice: M000963I
Discontinuance	CMODUSB	CMODUSB+	21-May-2019	21-May-2019	EVKIT is No Longer Supported
Discontinuance	DS2250-32-16+	N/A	20-Nov-2019	19-Nov-2020	Part can no longer be manufactured
Discontinuance	DS2250-64-16#	N/A	20-Nov-2019	19-Nov-2020	Part can no longer be manufactured
Discontinuance	DS2250T-32-16+	N/A	20-Nov-2019	19-Nov-2020	Part can no longer be manufactured
Discontinuance	DS2250T-64-16+	N/A	20-Nov-2019	19-Nov-2020	Part can no longer be manufactured
Discontinuance	DS5000FP-16+	N/A	20-Nov-2019	19-Nov-2020	Part can no longer be manufactured
Discontinuance	MAX14601ETA+	N/A	20-May-2020	19-Nov-2020	Part can no longer be manufactured
Discontinuance	MAX14601ETA+T	N/A	20-May-2020	19-Nov-2020	Part can no longer be manufactured
Discontinuance	MAX14605ETA+	N/A	20-May-2020	19-Nov-2020	Part can no longer be manufactured
Discontinuance	MAX14605ETA+T	N/A	20-May-2020	19-Nov-2020	Part can no longer be manufactured
Discontinuance	MAX20040ATPB/VY+	MAX20040BATPA/VY+	21-May-2019	21-May-2019	The part was not released
Discontinuance	MAX20040CATPA/VY+T	MAX20040DATPA/VY+T	21-May-2019	21-May-2019	The part was not released
Discontinuance	MAX20788EFN+	N/A	21-May-2019	21-May-2019	The part was not released
Discontinuance	MAX20788EFN+T	N/A	21-May-2019	21-May-2019	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Jun-2019

Discontinuance	MAX30207ALB+	MAX30207CLB+	20-May-2020	19-Nov-2020	The part was not released
Discontinuance	MAX30207ALB+T	MAX30207CLB+T	20-May-2020	19-Nov-2020	The part was not released
Discontinuance	MAX44000EVKIT#	N/A	21-May-2019	21-May-2019	EVKIT is No Longer Supported
Discontinuance	MAX44000GDT+T	N/A	21-Oct-2019	19-Nov-2020	Part can no longer be manufactured
Discontinuance	MAXQ610B-UEI+	N/A	20-May-2020	19-Nov-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2016+	N/A	20-May-2020	19-Nov-2020	Part can no longer be manufactured
Discontinuance	STM1E-SFP03	N/A	21-May-2019	21-May-2019	Part can no longer be manufactured
Discontinuance	STM1E-SFP12	N/A	21-May-2019	21-May-2019	Part can no longer be manufactured
Discontinuance	STM1E-SFP15	N/A	21-May-2019	21-May-2019	Part can no longer be manufactured
Discontinuance	VT240WFCR-ADJ	VT240WFCX-ADJ	21-May-2019	21-May-2019	Part can no longer be manufactured